

ECS Configuration Change Request

Page 1 of

Page(s)

1. Originator Maryellen Corbett	2. Log Date: 04/14/03	3. CCR #: 03-0265	4. Rev: —	5. Tel: 0703	6. Rm #: 2072C	7. Dept. SED
8. CCR Title: ClearCase BLM Baseline Update #6						
9. Originator Signature/Date Maryellen Corbett /s/ 04/14/03			10. Class II	11. Type: CCR	12. Need Date: 05/15/2003	
13. Office Manager Signature/Date Carolyn Whitaker /s/ 04/14/03			14. Category of Change: Initial ECS Baseline Doc.		15. Priority: (If "Emergency" fill in Block 27). Routine	
16. Documentation/Drawings Impacted (Review and submit checklist): See attached			17. Schedule Impact:		18. CI(s) Affected:	
19. Release Affected by this Change: N/A		20. Date due to Customer:		21. Estimated Cost: None - Under 100K		
22. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other:						
23. Problem: (use additional Sheets if necessary) Some baseline inconsistencies were noted in review of the XRP-II BLM and ClearCase BLM data.						
24. Proposed Solution: (use additional sheets if necessary) Document inconsistencies and provide red-lines for incorporation into ClearCase BLM where needed.						
25. Alternate Solution: (use additional sheets if necessary) None						
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Inconsistent baseline and installations						
27. Justification for Emergency (If Block 15 is "Emergency"):						
28. Site(s) Affected: <input type="checkbox"/> EDF <input checked="" type="checkbox"/> PVC <input checked="" type="checkbox"/> VATC <input checked="" type="checkbox"/> EDC <input checked="" type="checkbox"/> GSFC <input checked="" type="checkbox"/> LaRC <input checked="" type="checkbox"/> NSIDC <input checked="" type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
29. Board Comments:			30. Work Assigned To:		31. CCR Closed Date:	
32. EDF/SCDV CCB Chair (Sign/Date): Byron V. Peters /s/ 4/16/03			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
33. M&O CCB Chair (Sign/Date): Gary Gavigan /s/ 4/22/03			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
34. ECS CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS			

ADDITIONAL SHEET

CCR #: 03-0265 **Rev:** — **Originator:** Maryellen Corbett

Telephone: 0703 **Office:** 2072C

Title of Change: ClearCase BLM Baseline Update #6

CM Documents:

COTS Version baseline 910-TDA-003
Critical COTS List 910-TDA-023
HW/SW Maps 920-TDx-002
Systems Infrastructure Map 920-TDP-003 & 920-TDV-003
OS and COTS Patch MAP 920-TDx-014

Baseline ONLY Updates:

1. Add /tools/admin/find_ddos as a path for the automounted COTS software Find_DDOS 4.2 for all VATC hosts. The installation did not use the recommend path.
2. Remove HiPPI SW from the baseline of t1acg04. This host is an Origin 300 and does not support HiPPI.
3. Remove Sybase Replication Server and Replication Server Manager 11.5.1 from the COTS version map. With recent updates of the PVC string 1 machines, this version is no longer installed on ECS systems.
4. The path for Sybase Replication Server & Manager needs to be changed to /usr/ecs/OPS/COTS/sybase/REP-12_5
5. Add Sendmail 8.11.6+Sun to the baseline of t0mss01 and t0ins01 to identify for audit purposes that these host should be an active sendmail server. The version is the bundled Solaris 8 sendmail version. Update the sendmail version on the COTS version map - version applies to all sendmail installations.
6. Update Purify version 2002a.06 to 2002a.06.00 to conform to audit interrogation string returned.
7. Remove Volume Manager from baseline of p0mss02. Failover RAID cannot be effectively configured for this host and is no longer needed.

System Administrator Updates:

1. On t0ins01:
 - a. Remove obsolete versions of Netscape Enterprise Server 3.6 installed in the following paths:
/usr/ecs/OPS/COTS/ns-home
/usr/ecs/OPS/COTS/www/ns-home
 - b. Remove obsolete version (1.2 & associated patch) of Tripwire. The baseline version (1.3.1) is correctly installed.
 - c. Remove Apache 1.3.26
2. On t0mss01:
 - a. Remove obsolete versions of Netscape Enterprise Server 3.6 installed in the following paths:
/usr/ecs/OPS/COTS/ns-home
/usr/ecs/OPS/COTS/www/ns-home
 - b. Remove obsolete version (1.2 & associated patch) of Tripwire. The baseline version (1.3.1) is correctly installed.
3. On t1acg04:
 - a. Install BDSpro 2.3 with patch identified in PSR # 914-TDA-227, removing obsolete version 2.1p0 install in the /usr/etc directory.
4. On t1acs02:
 - a. Remove obsolete version (1.2 & associated patch) of Tripwire. The baseline version (1.3.1) is correctly installed.
5. On t1acs03:
 - a. Remove obsolete version (1.2 & associated patch) of Tripwire. The baseline version (1.3.1) is correctly installed.
6. On t1ais01:
 - a. Remove obsolete version 4.2 of Sun Workshop compilers from path /opt/SUNWspro/bin
 - b. Remove obsolete version (1.2 & associated patch) of Tripwire. The baseline version (1.3.1) is correctly installed.
7. On t1acg04, install BDSpro 2.3, removing obsolete version 2.1p0.
8. Uninstall Volume Manager 2.6 from p0mss02. Failover RAID cannot be effectively configured for this host and is no longer needed.

